


Homogeneous Area: M02

Material: Gaskets

Description: Gaskets in the flanged fittings throughout the HVAC system

Locations, amount and asbestos content:

Location	Amount	Asbestos Content
Boiler Room and Pipe Chases	~100 exposed in boiler room, undetermined quantity in remainder of the HVAC system	65% Chrysotile



Example of flanged fitting gaskets.