

SECTION 6 - HOMOGENEOUS AREAS

Note: A list of asbestos containing material still present in the building is located in the most recent AHERA Re-inspection Report located in Section 3.

AHERA requires that material be separated into homogenous areas and functional areas, and that each homogeneous area be described by text or on a floor plan in the management plan. Each homogeneous area is assigned a number. The following Section provides information on the homogeneous areas that have been identified at the school building since AHERA regulations came into effect.

Some of these materials have since been sampled and determined not to contain asbestos, sampled and proven asbestos, or removed during an abatement or renovation activity. Some materials, such as fire doors, are still assumed to contain asbestos due to the difficulty in sampling the material or the fact that sampling will compromise the integrity.

A list of samples and analytical results from prior sampling events is included as part of the historical documentation; however, these lists are no longer being maintained. Results from all known sampling events have been tabulated and are maintained in Section 5 of this Management Plan.