

Homogeneous Area: S01

Material: Surfacing Overspray

Description: Plaster overspray

Locations, amount and asbestos content:

Location	Amount	Asbestos Content
On the galvanized steel ducts above the ceilings of the entry hallway and testing room North of the auditorium	~10 ft ²	8% Chrysotile

